

## **CERTIFICATE OF CONFORMITY**

No. CLS1B 15 02 81381 017

Certificate Holder: Samcom Electronics Pte Ltd

89 Kaki Bukit Avenue 1 Shun Li Industrial Park Singapore 417957 SINGAPORE

**Certification Mark:** 

TÜV SÜD PSB

**Product:** Emergency Lightings

Brand Name: SAMCOM

**Model(s):** (1) EEP18P (2) EEW18

Product Rated: 230V 50/60Hz

**Details:** Load : 1 x 8W T5 FLUORESCENT

Battery: 2.4V 2.5AH NI-CD

Duration: 1.5 Hrs

IP 65 applicable for model EEW18 only

**Standard(s):** SS 263-2/A2:2008

SS 563-2/A1:2013 (cl 6, 8, 9, 10.6 & 10.7)

Country of Origin: Singapore

**Test Report(s):** See CoC Appendix (1pg)

Issued on: 2015-02-04

Valid until: 2018-02-03

Products listed under Class 1B must have TÜV SÜD PSB PLS mark as shown above affixed/printed on them. Failure to comply with this requirement may result in revocation of this certificate.

Vice-President (Certification Department)
TÜV SÜD PSB

Charle

Page 1 of 2

This Certificate is part of a full report and should be read in conjunction with it. This Certificate remains the property of TÜV SÜD PSB Pte Ltd and shall be returned upon request. The use of this Certificate is subjected to TÜV SÜD Group Testing and Certification Regulations; TÜV SÜD PSB Pte Ltd (PSB) General Terms and Conditions of Business and PSB Product Listing Scheme (PLS) Application Fact Sheet. The manufacturer is solely responsible for compliance of any product that has the same designation as the product type-tested. Persons relying on this Certificate should verify its validity by checking TÜV SÜD PSB's website at www.tuv-sud-psb.sg



## PRODUCT LISTING SCHEME APPENDIX

TO CERTIFICATE OF CONFORMITY NUMBER: CLS1B 15 02 81381 017

Date of Issue

2015-02-04

Issued To

Samcom Electronics Pte Ltd

89 Kaki Bukit Avenue 1 Shun Li Industrial Park Singapore 417957 SINGAPORE

Test Report(s)

7191095134-EEC14/01-HPW 7191095134-EEC14/02-HPW

7191095134-EEC14/03-HPW 7191095134-EEC14/04-HPW

> Vice President (Certification Department) TÜV SÜD PSB

Page 2 of 2

Amendments or additions to this appendix other than those authorised by TÜV SÜD PSB Pte Ltd render the appendix invalid.